



Maintenance Menu



P.O. Box 277
Wyoming, MN 55092

651-462-4516

Annual Maintenance + Impeller

Recommended every 3 years

4 Stroke - **\$546 + Parts**

2 Stroke - **\$468 + Parts***

- Oil / Filter Change*
- Gear Lube Change
- Inspect Spark Plugs
- Inspect Thermostats
- Inspect Timing Belt*
- Inspect Shift / Throttle Linkage
- Inspect Power Trim
- Replace Fuel Filters
- Check Computer Diagnostic
- Grease Motor / Pivot Points
- Check Idle Speed
- Check Motor Mount Bolts
- Inspect Steering
- Replace Water Pump Impeller

*Some Exceptions Exist
Average price based on a 2019
Yamaha T50 = **\$710**

Annual Maintenance

4 Stroke - **\$312 + Parts**

2 Stroke - **\$234 + Parts***

- Oil / Filter Change*
- Gear Lube Change
- Inspect Spark Plugs
- Inspect Thermostats
- Inspect Timing Belt*
- Inspect Shift / Throttle Linkage
- Inspect Power Trim
- Replace Fuel Filters
- Check Computer Diagnostic
- Grease Motor / Pivot Points
- Check Idle Speed
- Check Motor Mount Bolts
- Inspect Steering

*Some Exceptions Exist
Average price based on a 2019
Yamaha T50 = **\$445**

Winterize Only

Outboard - **\$208.95**

Change gear oil, replace lower unit washers,
condition fuel, grease fittings, drain carbs/
VST, disconnect starting battery

Stern Drive - **\$261.63**

Drain block and or run on anti-freeze,
change gear oil, replace lower unit washers,
condition fuel, grease steering, disconnect
starting battery

Oil Change Only

**\$124.8 + Oil &
Filter Oil \$9.50 / Qt**

Acid Wash

Pontoons - **\$160 / Tube**

Boat Hull - **\$375**

Trailer Wheel Bearing

Repack - **\$200 + Parts**

Replace - **\$200 + Parts**

Trailers with breaks - **\$156 / hr**

PER AXLE

Prices subject to change.

Sales tax Applicable.

1/2 hour minimum labor.

4 Stroke PWC / Inboard Jet Boat Maintenance

Winterize - **\$210**
Oil Change - **\$124.8 + Parts**
Spark plugs are
recommended every
3 years

Inboard Boats

Winterize - **\$606**
Oil Change - **\$124.8 + Parts**
Winterizing ballast bags,
ballast tanks, showers,
heaters, or freshwater tanks
are an additional **\$60**

Storage Pricing Fall '23 to Spring '24

Under 15'11" **\$375**
16' to 17'11" **\$450**
18' to 19'11" **\$525**
20 to 21'11" **\$600**
22 to 23'11" **\$700**
24' to 27'11" **\$800**
28' to 32' **\$875**
PWC / Jet Ski **\$375**

*35% increase for boats wider
than 8'6"

Outboard Maintenance

Winterize - **\$208.95**
Oil Change - **\$124.8 + Parts**
Fuel Filter - **\$50 + Parts***
Spark Plugs - **\$50 + Parts***
Water Pump - **\$234 + Parts***
Clean Fuel Injectors
4 Cylinder - **\$156 + Parts***
6 Cylinder - **\$234 + Parts***
8 Cylinder - **\$312 + Parts***
Carb Clean - **\$234 Per Carb + Parts**
Drain Fuel Tank - **\$156**
Computer Diagnostic Report - **\$78**
Diagnostic work - **\$156 per Hour**
Diagnostic Lake Test - **\$312**
Spring Start Up - **\$205**

Currently working on 2002 &
newer outboards

We no longer service
Johnson / Evinrude
motors*

***Some Exceptions Exist**

I/O Maintenance

Winterize - **\$261.53**
Oil Change - **\$124.8 + Parts**
Fuel Filter - **\$46.8 - \$78 + Parts***
Spark Plugs - **\$78 - \$312 + Parts***
Cap & Rotor - **\$78 - \$234 + Parts***
Thermostat - **\$78 - \$312 + Parts***
Water Pump Alpha 2 - **\$234 + Parts***
Sea Water Pump - **\$234 - \$468 + Parts***
Gimble Bearing & U-Joint
Check - **\$156 - \$234***
Replace - **\$312 - \$468***
Computer Diagnostic Report - **\$78**
Spring Start Up - **\$205**

Winterizing freshwater
tanks or sinks are an
additional **\$60**

Currently working on Volvo
Penta with SX drives and
newer, MerCruiser Alpha II or
Bravo 1996 and newer.

***Some Exceptions Exist**